



1636 West North Temple • Salt Lake City, UT 84116 • 801-533-6071

* MEMORANDUM *

TO:

File

FROM:

Richard B. Hall, Distribution Engineer

SUBJECT: Field Examination of the Big Sand Wash Distribution System

DATE:

September 14, 1984

A field examination of the subject system was undertaken on September 13, 1984, with the following in attendance:

Bill Christensen Edward D. Feldt

Richard B. Hall Jerry L. Bronicel

The following items were observed:

- 1) The measuring devices in the ditches are in satisfactory condition.
- 2) The parshall flume immediately below the dam is not accurate because the upstream velocities are way to high.
- The system has several small rights immediately upstream of the 3) reservoir.